

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Ashford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 70 Perry Hill Road	8/21/2002	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP discussed with the environmental consultant additional sampling data obtained for nearby threatened wells that shows there was no pollution in the wells. DEP requested that the data be submitted for detailed review.	Action pending.

### Avon

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Avon Municipal Landfill Huckleberry Hill Road	7/5/2007	Pollution was detected in a supply well but is below standards.	DEP directed the town to identify wells within 500 feet and continue to conduct an already approved landfill monitoring program.	Sampled residential wells and installed new monitoring well for landfill. Monitoring program continuing.
Village Cleaners and Tailors 183 West Main Street	11/22/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well, identify supply wells within 500 feet, and sample any identified wells for pollutants detected at the site.	Five wells identified within 500 feet but they are upgradient and not at risk. Volatile organic compounds not detected in on-site drinking water supply well. Site is undergoing investigation and remediation under Property Transfer Program.

### Barkhamsted

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Hitchcock Chair Company - "Plant 2" 13 Riverton Road	7/26/2007	Petroleum above the groundwater protection criteria threatens a supply well within 500 ft.	DEP directed the property owner to submit a post-remedial monitoring report to document impact is not migrating off-site.	Removed impacted soil, monitoring 20 wells semi-annually for natural attenuation of TPH.

### Berlin

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Best Cleaners 138 Mill Street	1/23/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP required additional sampling of a nearby identified well and identification of any other drinking water wells within 500 feet of the site.	Additional investigation confirmed and further defined hazard condition; mitigation action pending.
EIS Brake Parts (former) 129 Worthington Ridge	3/4/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Bethany

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Chemtura - Bethany Ag. R&D Facility 74 Amity Road	9/4/2007	Pollution was detected in a supply well (not used for drinking) above standards, and in another supply well below standards.	The property owner provided a survey of wells in the vicinity with the notification. DEP directed the property owner to provide additional technical information, and a work plan to sample a subset of wells identified in the vicinity of the site.	All on-site wells were resampled, including supply wells, and no chemicals of concern were detected above drinking water standards. Given this additional info, DEP concluded that it would not be necessary to sample off-site water supply wells.
Pleasant View Garage 119-127 Amity Road	5/26/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the identified nearby wells for pollutants detected at the site.	Action pending.

### Bethel

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mountain Laurel Plaza 66-68 Stony Hill Road	6/8/2006	Pollution was detected in a drinking water well but is below standards; pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample both on-site supply wells and to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Two on-site and off-site water supply wells identified. Pollution was not detected in two on-site and one off-site well tested. Monitoring program implemented.
parcel 82 Stony Hill Road	2/16/2007	Pollution was detected in a drinking water well but is below standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to re-sample the onsite supply well and the monitoring well at the septic system for pollutants detected at the site.	Action pending.

### Bethlehem

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 135 and 147 Main Street South	5/5/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to resample the monitoring well and to sample the on-site well for pollutants detected at the site.	All wells sampled, pollution not detected or detected significantly below standards. No additional hazard abatement action necessary.

### Bolton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mike's Citgo 1135 Boston Turnpike	6/3/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Bolton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Precision Landscaping 280 West Street	2/21/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Wells identified and sampled, pollution either not detected or detected but below standards.

### Branford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Branford Landfill Marshall Road	5/6/2003	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP reviewed information provided and determined that the groundwater pollution does not actually discharge to the nearby surface water. The pollution does not in fact threaten aquatic life.	No specific hazard abatement action necessary. Monitoring to continue pursuant to Landfill requirements.
Shoreline Trailer Court Mobile Home 509-545 East Main Street	10/19/2004	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP determined that remediation already in progress will address the hazard.	Site has been remediated pursuant to an engineered control that effectively eliminates direct contact with pollutants. No additional hazard abatement action necessary.

### Bridgeport

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Black Rock Ship Yard (former) 10 Brewster Street	11/14/2005	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the owner to arrange for the prospective purchaser to include evaluation of the threat to surface water and aquatic life in planned investigation and remedial activity.	Action pending.
Braxton Men's Shop 1168 Stratford Avenue	2/2/2004	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP reviewed sampling data and determined that the groundwater pollution does not in fact pose a significant threat to indoor air quality.	No specific hazard abatement action necessary.
Conco Medical 380 Horace Street	8/21/2002	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that access to the site and polluted soils is restricted, limiting the potential for contact. DEP requested that all persons with access be made aware of the condition.	Access to polluted soil is restricted; no specific hazard abatement action necessary.
former BP Service Station No. 5089 3956 Main Street	4/3/2003	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP's Leaking Underground Tank Program is working with the property owner to investigate the site. DEP initiated an investigation of soil vapor beneath the building. DEP letter (4/7/06) requested active groundwater remediation.	Sampling of indoor air quality shows that air pollution is not at levels that pose a significant risk.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Bridgeport

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
former Remington Arms Company, Inc. 939 Barnum Avenue	1/16/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs and install a fence or secure the area to limit access to the polluted soil.	Warning signs posted, site secured and fence installed to limit the potential for contact with polluted soil.
former Remington Arms Company, Inc. 939 Barnum Avenue	2/5/2004	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to evaluate the nature, extent and degree of groundwater pollution to determine the threat to surface water and aquatic life near the site.	Groundwater threat to surface water evaluated for site specific conditions and determined to not significantly impact surface water and aquatic life.
General Electric Company - Bridgeport 1285 Boston Avenue	7/29/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the site is secure, limiting the potential for contact.	Access to polluted soil is restricted; no specific hazard abatement action necessary.
		Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to submit a plan to evaluate the threat to surface water, aquatic life, and sediment quality.	Action pending.
General Electric Company - Bridgeport 1285 Boston Avenue	1/25/2007	Pollution detected in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the site is secure, limiting the potential for contact.	Access to polluted soil is restricted; no specific hazard abatement action necessary at this time.
		Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to submit a plan to evaluate the threat to surface water, aquatic life, and sediment quality.	Action pending.
General Electric Company - Bridgeport 1285 Boston Avenue	8/20/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the site is secure, limiting the potential for contact.	Access to polluted soil is restricted; no specific hazard abatement action necessary.
Post Office Arcade Mall 991-1019 Main Street	6/25/2007	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP reviewed sampling data and determined that the groundwater pollution does not in fact pose a significant threat to indoor air quality.	No specific hazard abatement action necessary.

### Bristol

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Bank of America 26 East Main Street [Forestville]	11/15/2005	Groundwater polluted with fuel oil above standards may threaten a drinking water well.	DEP directed the property owner to implement their proposed plan which includes conducting an inventory of wells within 500 feet of the site. Additionally, DEP required the property owner to sample for fuel oil any wells identified in the inventory.	Supply well inventory completed. No drinking water supply wells identified within the 500 foot radius requested. Additionally, monitoring wells were installed on site and sampled.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Bristol

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Peabody Landscaping 53 Mines Road	10/18/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample identified nearby wells for pollutants detected at the site.	Wells identified and sampled. Laboratory analytical results indicated no site related pollutants detected in the supply wells.
		Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP reviewed sampling data and determined that the groundwater pollution does not in fact pose a significant threat to indoor air quality.	No specific hazard abatement action necessary.
Pump Station 13 Julia Road	12/1/2004	Pollution was detected in a drinking water well above standards.	DEP reviewed additional sampling data and determined the reported pollution was not confirmed. DEP directed the property owner to sample the potentially affected wells monthly for pollutants detected at the site, and provide bottled water if needed.	Monitoring program implemented.
Yankee Gas Service Company Riverside Avenue	5/9/2006	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is in a secure and fenced area, limiting the potential for contact.	Access to polluted soil is restricted; no additional hazard abatement action necessary.

### Brookfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
A. J. Tuck Company 32 Tuck Road	1/3/2007	Pollution was detected in two drinking water wells but is below standards.	DEP directed the property owner to sample the on-site supply well and an off-site supply well (at 34 Tuck Rd) on a quarterly basis and to identify wells up to 500 feet away from the site.	Action pending.
A'von Auto and Equipment 303 Federal Road	6/29/2004	Pollution was detected in a drinking water well above standards.	DEP reviewed additional sampling data for the well and determined that pollution is not in fact present, and water is safe for human consumption.	No additional hazard abatement action necessary.
Brookfield Square 270 Federal Road	11/30/2004	Pollution was detected in a drinking water well but is below standards.	DEP is sampling adjacent wells and directed the property owner to identify wells up to 500 feet away from the site for pollutants detected at the site, and to recommend further actions.	Action pending.
Elmbrook Plaza 632 and 640 Federal Road	5/9/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells onsite and up to 500 feet away from the site for pollutants detected at the site.	7 wells identified and 7 wells sampled. Pollution not detected. No additional hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Brookfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Greentree Toyota (former) 465 Federal Road	4/27/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the on-site and nearby identified wells within 500 feet for pollutants detected at the site.	All wells sampled, pollution either not detected or detected but below standards. No additional hazard abatement action necessary. Investigation and remediation on-going at site.
Kimchuk (former) 34 Del Mar Drive	5/20/2005	Pollution was detected in a drinking water well above standards.	DEP required no action, because there is already a treatment filter on the supply well and nearby locations also have alternate supplies of potable water.	DEP and the local health department are further evaluating this historic condition to determine if additional actions are needed.
Rapid Power Technologies 18 Old Grays Bridge Road	2/14/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 1000 feet away from the site for pollutants detected at the site.	No wells within 500 feet. Six wells within 1,000 feet were sampled. Pollution was not detected. Two wells sampled quarterly as required by Department of Public Health. Source of pollution removed. No additional hazard abatement action necessary.
Shell Facility No. 136291 49 Federal Road	1/10/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	The Town of Brookfield, under a consent order with the DEP, is currently monitoring those wells of concern.
Shell Facility No. 136291 (former) 49 Federal Road	7/7/2009	Pollution was detected in a drinking water well above standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to provide an alternate supply of potable water for polluted on-site water supply well and to continue monitoring this well on a quarterly basis.	Action pending.
shopping plaza 106 Federal Road	5/30/2006	Pollution was detected in a drinking water well above standards.	DEP reviewed information provided and determined the affected well already has a monitored treatment system.	Pollution above standards in on-site well and closest downgradient well. Filtration systems installed. Monitoring program implemented for all wells.
		Polluted groundwater and soil beneath an occupied building could affect indoor air quality.	DEP directed the property owner to determine if indoor air quality is being affected and provide a plan of action.	Building vacant where standards exceed criteria. DEP to be advised of change in occupancy.
shopping plaza 106 Federal Road	5/8/2008	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to sample the on-site water supply well and two nearby water supply wells on a quarterly basis for the pollutants detected at the site.	Monitoring program implemented.
ShopRite Plaza 143 Federal Road	8/30/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample identified wells within 500 feet for pollutants detected at the site.	Eight wells identified within 500 ft:- 3 are unoccupied residential lots. Public supply wells at ShopRite and Country Kids Club are already monitored by DPH. Remedial investigations currently being conducted.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Brookfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Sunland Marine 419 Federal Road	8/21/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample nearby wells for pollutants detected at the site.	Action pending, awaiting access permission for sampling.
Texaco Facility No. 100058 138 Federal Road	1/10/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	All wells sampled, pollution not detected or significantly below standards.
Wentworth Laboratories 500 Federal Road	9/26/2008	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to re-sample the onsite supply well and identify wells up to 500 feet away from the site.	Drinking water well re-sampled and inventory of supply wells conducted. Re-sampling of well confirmed low level of Barium, significantly below standards. No additional sampling necessary for hazard evaluation or abatement.

### Brooklyn

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Eggs, Inc. Route 205 and Vina Lane	5/27/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	Action pending.

### Canaan

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Falls Village CITGO (PC#007710) Junction Route 7 and Route 63	3/30/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well on a quarterly basis until remediation of the site is complete and to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Nearby wells tested and no pollution detected. Quarterly monitoring program on-going for on-site supply well, monitoring wells, and surface water. DPH also reviewing data.
Hitchcock Brothers, Inc. 78 High Street	2/21/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed potable water supply well sampling data. Pollution is not in fact present in the well and does not pose a risk to supply wells.	Monitoring data shows threatened well not affected. No additional hazard abatement action necessary.

### Canterbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Willimantic Waste Paper Co. 133 Packer Road	5/27/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Consultant identified potable wells within 500 foot radius. Sampled 5 wells; one additional house appeared to be vacant and was not sampled. No contaminants detected.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Canton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Chruch of Jesus Christ of Latter-Day Saints 27 Lawton Road	5/22/2007	Explosion hazard exists due to the release of propane from a storage tank	DEP directed the property owner to continue to monitor threatened residential properties for volatilization and explosion risks.	Monitoring wells were sampled and levels within wells no longer exhibit explosion hazard. No additional hazard abatement action necessary.
unknown source Albany Trunpike/Dunham Road	4/15/2009	Pollution was detected in a drinking water well above standards. Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to provide bottled water to any future tenant at 198 Albany Turnpike / 12 Dunham Road. DEP indicated it will collect a confirmation sample to verify contaminant is present within the drinking supply well.	Impacted well tested twice; both times contaminants of concern were not detected.

### Chaplin

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Chaplin Mobil 17 Willimantic Road	8/13/2008	Pollution detected in groundwater above standards may threaten nearby drinking water wells.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at site.	Action pending.
Fin Fur and Feather Club 213 Chewink Road	4/5/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the threatened well quarterly for the pollutants detected at the site, and advise DEP of any changes, and provide a plan to abate the hazard.	Treatment system installed at threatened downgradient property 7/5/07. Abatement plans proceeding.

### Cheshire

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Cheshire BP 901 West Main Street	7/29/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite and identified wells within 1000 feet for pollutants detected at the site.	Action pending.
Cheshire Landfill Route 70	12/3/2002	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to sample wells up to 100 feet from the site for pollutants detected at the site.	Additional sampling conducted, pollution below standards.
Cheshire Landfill Route 70	5/23/2005	Pollution was detected in a drinking water well but is below standards.	DEP required continued sampling of the well for pollutants detected at the site.	Monitoring to continue pursuant to Landfill requirements.
Cheshire Landfill Route 70	11/28/2005	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to continue an established monitoring program, and evaluate trends in the pollutant that was detected.	Monitoring to continue pursuant to Landfill requirements.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Cheshire

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Cheshire Veterinary Hospital 1568-1572 South Main Street	9/29/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample wells up to 500 feet away from the site for pollutants detected at the site.	Property owner has conducted an inventory of wells within 500 feet.
residence 485 Moss Frams Road	5/20/2008	Pollution was detected in a drinking water well but is below standards.	DEP directed the Town of Cheshire to continue an established monitoring program, and evaluate trends of the pollutant that was detected.	The Town of Cheshire has sent a letter notifying the owner of the MTBE detection. The well was resampled on May 2, 2008 and volatile organic chemicals, including MTBE were not detected.
residential property 2298 Waterbury Road (aka 2289)	2/22/2005	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to identify and sample wells onsite and up to 500 feet away from the site for pollutants detected at the site.	Wells identified and sampled. No pollutants associated with this notification detected above standards.

### Chester

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 62 Spring Street	4/5/2005	Pollution by fuel oil was detected in a shallow drinking water well.	DEP reviewed actions taken and determined they adequately addressed the pollution problem.	A new drinking water well had already been installed in an area not affected by the pollution. No additional hazard abatement action necessary.
Roli Enterprises LLC 20 Denlar Drive	1/29/2004	Pollution was detected in a drinking water well but is below standards.	DEP reviewed sampling data and determined pollution in the well is significantly below standards, and the water is safe for human consumption.	Building currently vacant. No specific hazard abatement action necessary. DEP recommended periodic monitoring of well.

### Colchester

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Columbia Cleaners (former) 67 Lebanon Avenue	11/15/2006	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to submit a plan to characterize the impact on indoor air quality and develop a remedy to limit the impact.	Proposal to determine extent of contamination and install sub-slab venting system is pending. Nearby drinking water supply wells identified and tested; no impact found. Investigation/remediation (if needed) to continue under Property Transfer Program.

### Columbia

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Collins Garage 177 Route 66	6/10/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and sample nearby wells for pollutants detected at the site.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Coventry

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
7-Eleven Store # 32520 2711 Boston Turnpike (Route 44)	10/23/2007	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.
Coventry Landfill Route 31	5/27/2003	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP reviewed information provided and determined that the groundwater pollution does not in fact significantly threaten aquatic life.	No specific hazard abatement action necessary. Monitoring to continue pursuant to Landfill requirements.
Coventry Landfill Route 31	6/3/2004	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP reviewed information provided and determined that the groundwater pollution does not in fact significantly threaten aquatic life.	No specific hazard abatement action necessary. Monitoring to continue pursuant to Landfill requirements.
residence (former farm) 10 Grant Hill Road	2/26/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the identified wells within 500 feet to the west, south and east of the site for the pollutants present on the site.	Action pending.

### Cromwell

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
former Scheu Nursery Intersection Geer and Woodside Streets	12/10/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined there was in fact no significant hazard risk for the current land use. DEP also directed the property owner to identify and sample wells within 500 feet for pollutants detected at the site.	Polluted soil was removed from the site during development; no additional hazard abatement action necessary. Drinking water wells were identified and sampled and no pollutants associated with the site were detected; no further monitoring required.
Shell Facility No. 136296 (former) 131 Berlin Road	8/15/2005	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to resample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	A treatment system was installed on the affected well. No pollutants above standards were detected in the remaining drinking water supply wells along nearby Kirby Road.
Sunoco 164 West Street	11/10/2005	Pollution was detected in a drinking water well but is below standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the threatened well quarterly for the pollutants detected at the site.	Action pending, water supply well to be sampled quarterly.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Danbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
345 Main Street LLC 354 Main Street	3/5/2008	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to determine if indoor air quality is being affected and provide a plan of action, if necessary.	Action pending.
Aberdeen property 11-27 East Franklin Street	4/4/2006	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	As an interim measure, DEP directed the property owner to inform persons with potential for exposure, post warning signs and install a fence to limit access to the polluted soil until the site is cleaned up.	Polluted soil was removed; no additional hazard abatement action is necessary.
Alliance Energy Corp 112 Federal Road	2/14/2003	Pollution was detected in a drinking water well above standards.	DEP reviewed additional sampling data and determined that pollution is actually below standards, and the water is safe for human consumption.	Water treatment system installed. No additional hazard abatement action necessary.
Amphenol Corporation 33 East Franklin Street	3/18/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is under pavement and in a secure and fenced area, limiting the potential for contact.	No additional hazard abatement action necessary.
CL&P Triangle 11A Substation Triangle Street	11/8/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact.	Warning signs posted; site is secure fenced electrical substation limiting the potential for contact with polluted soil; no additional hazard abatement action necessary.
Colonial Ford Prep Center 93 Sand Pit Road	2/24/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to verify the existence of, and sample, nearby wells for pollutants detected at the site.	Two wells identified and sampled. One year monitoring program implemented. Pollution not detected or detected significantly below standards. No additional hazard abatement action necessary.
commercial property 32-34 Newtown Road	5/31/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the two identified downgradient wells for pollutants detected at the site and to provide an alternate supply of potable water/treatment for properties with polluted wells.	Action pending.
Exxon Station (former) 112 Federal Road	2/28/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the off-site threatened well, unless arrangements have been made to connect the location to public water.	Property connected to public water and well properly abandoned. No additional hazard abatement action necessary.
John's Automotive Service Center 85 Mill Plain Road	4/22/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP required additional sampling of on-site water supply well for pollutants detected at the site.	On-site well sampled. Pollution not detected. Monitoring program implemented.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Danbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mobil Service Station No. 01-GFO 112 Newtown Road	2/9/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the five nearest threatened wells and provide bottled water to occupants if results exceed standards.	Four water supply wells on nearby Claremont Terrace were sampled 5/2005 and 5/2006. Chloroform (not associated with gasoline) was detected in two of the wells. "Sentinel" bedrock well installed between plume and residences are sampled quarterly.
Norbert E. Mitchell Co., Inc. 7 Federal Road	7/6/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to periodically sample the onsite well for pollutants detected at the site, until polluted soil on the site is remediated. (No other drinking water wells were identified within 500 feet of the site.)	One water supply well identified (on-site well) and sampled, pollution not detected. Semi-annual monitoring program implemented.
residence 5 Timber Crest Drive	1/27/2009	Pollution was detected in a drinking water well above standards.	DEP reviewed additional sampling data for the affected well and determined pollution is not in fact present in the well. DEP directed the property owner to continue to sample the well and to advise DEP of any changes.	One water supply well resampled; pollution not detected. Monitoring program to be implemented.
residential property 24 Pond Crest Road	9/24/2002	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional sampling data and determined that the well at risk was not polluted and recommended periodic sampling of the well until remediation is complete.	Source of pollution removed. No additional hazard abatement action necessary.
residential property 216 Westville Avenue Extension	1/15/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional sampling data showing that the well at risk was not polluted.	Source of pollution removed. No additional hazard abatement action necessary. DEP recommended periodic sampling of the well.
residential property 11 Sturdevant Drive	9/21/2004	Pollution was detected in a drinking water well above standards.	DEP required additional sampling of on-site and nearby wells for pollutants detected at the site.	Source of pollution removed. Additional sampling found no detectable pollution. No additional hazard abatement action necessary.
Texaco Facility No. 100061 3 Mountainview Terrace	10/15/2002	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Twelve wells identified and ten wells sampled. Pollution not detected or significantly below standards. Source of pollution removed. No additional hazard abatement action necessary.

### Darien

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 31 Hancock Lane	2/10/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample on-site and nearby wells for pollutants detected at the site.	At-risk supply wells sampled and no pollution detected. Groundwater remediation implemented. No additional hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Deep River

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
parcel 168 Main Street	11/10/2003	Pollution was detected in a drinking water well but is below standards.	DEP identified a responsible party and required provision of a safe supply of drinking water.	Water treatment system installed by responsible party at property with polluted well. No additional hazard abatement action necessary.

### Derby

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
former DoT property Main Street	1/24/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to submit a plan to eliminate the risk to human health.	Polluted soil removed; no additional hazard abatement action necessary.

### Durham

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Alliance Energy 24 Main Street	1/18/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to resample the well on-site and to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Alliance sampled on-site supply well and wells 500 feet away from the site for the pollution detected at the site. A treatment system was installed on one well documented above standards. Alliance will continue to monitor this system.
Durham Firehouse 41-51 Main Street	9/10/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	As requested, the town identified and sampled one well within 500 feet and found no contamination.
Grippe's Mobil 349 Main Street	1/26/2006	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Property owner responded indicating no action is necessary.
residential property 220 Main Street	8/29/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells onsite and up to 500 feet away from the site for pollutants detected at the site.	Pollution source removed, surrounding residences within 500 feet sampled for petroleum. No concentrations of petroleum were detected in excess of laboratory detection limits.
Shell Facility No. 136301 (former) 336 Main Street	7/7/2009	Pollution was detected in a drinking water well above standards. Pollution detected in groundwater above standards may threaten four drinking water wells located within 500 feet.	DEP required additional sampling of onsite and other three nearby identified wells for metals detected at the site.	A well receptor survey within a 500-foot radius of the site was conducted and four potable wells were identified. All four wells have been sampled regularly since 1995 and they are on water treatment system installed by DEP before.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### East Granby

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
East Granby Citgo 2 School Street	4/28/2008	Petroleum and metals detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the threatened wells for the pollutants detected at the site, and advise DEP of any changes. DEP also required the owner to continue to evaluate and characterize soil and groundwater impacts.	Private supply well sampling pending.

### East Haddam

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
7-Eleven Store # 32526 4 Falls Road	7/29/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to continue routine sampling of the onsite supply well and to identify and sample wells up to 500 feet downgradient from the site for pollutants detected at the site.	Action pending.

### East Hampton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
commercial parcel 5 East High Street and 6 North Main Street	8/18/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Additional sampling conducted by the Town of nearby wells.
Ghezzi Motors (former) 13 Watrous Street	8/26/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Sampled on-site supply well. Laboratory analytical results reported pollutants not detected. Additional action off-site pending.
parcel 103 Main Street	8/26/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Additional sampling conducted by the Town of nearby wells.
Summit Thread Powerhouse (former) 13 Watrous Street	1/13/2009	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact.	No specific hazard abatement action necessary.
Water Tower Property Walnut Avenue	7/27/2006	Pollution was detected in a drinking water well above standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to provide an alternate supply of potable water for polluted wells and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Continued sampling of nearby wells and monitoring of the site. Sampling indicates exceedances of pesticides. Alternative water supply was provided by CTDEP.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### East Hampton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
West High Street area West High Street	10/31/2005	Pollution was detected in a drinking water well above standards.	DEP directed DoT to resample all wells that reported elevated concentrations, above standards, of arsenic or lead.	DoT resampled wells that had detected arsenic and lead, and bottled water is used at wells above standard.

### East Hartford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Pratt & Whitney Andrew Willgoos Turbine Laboratory Pent Road	10/31/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to maintain existing fencing that prevents access to polluted soil and to implement remediation following complete site assesment.	Fence was constructed to prevent access to polluted soil and warning signs were posted; remediation will occur following site assesment.
residence 79 Shawnee Road	1/8/2008	Polluted groundwater near an occupied building could affect indoor air quality.	DEP directed the property owner to conduct a soil gas study to determine if polluted groundwater poses a risk to indoor air quality.	Action pending.

### East Haven

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Cinque Industrial Park 509 Laurel Street	11/6/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to submit a plan to identify the extent of polluted soil, notify site occupants, and limit access to the polluted soil.	Property owner submitted plan for investigation.

### East Windsor

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Golden Gavel Auction House 149 North Road	2/3/2005	Pollution was detected in a drinking water well above standards, and other pollution detected in groundwater above standards may threaten this drinking water well.	DEP directed the property owner to provide bottled water as an alternate supply of potable water until resampling confirms the origin of the pollution reported.	Lead due to piping in residential property not groundwater. No additional hazard abatement action necessary since no environmental pollution.
Mobil Service Station No. 01-E53 (former) 276 Main Street	12/6/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to contiune with current plans for site investigation and remediation, and to sample nearby residential wells for the contaminants of concern.	Receptor survey conducted and drinking water supply wells surrounding subject property were sampled and were below the detection limit for the contaminants of concern.
Mobil Service Station No. 01-GAQ 157 North Road	9/14/2005	Pollution was detected in a drinking water well but is below standards, and pollution detected in groundwater above standards may threaten drinking water wells.	DEP directed the property owner to sample the polluted well quarterly for pollutants detected at the site, and sample identified downgradient wells.	Where access was granted the supply wells surrounding the subject property were sampled and were below the detection limit for the contaminants of concern. Continued to sample on-site well quarterly.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Easton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 78 Mile Common	10/14/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells onsite and up to 500 feet away from the site for pollutants detected at the site.	Source of pollution removed. The well water supply has been determined potable. No other wells within 500 feet of release area.

### Ellington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
CRRA Ellington Landfill Sadds Mill Road (Route 140)	9/15/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to continue to sample the threatened well and report results to DEP.	No specific hazard abatement action necessary; threatened well already monitored regularly and pollution not detected. Monitoring of well is ongoing under Landfill requirements.
Ellington Landfill Sadds Mill Road	6/5/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the landfill operator to continue quarterly sampling of monitoring wells and neighboring residential wells	Continuing monitoring program in accordance with a DEP consent order. Impacted residential properties are being supplied with bottled water and sampled quarterly.

### Enfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
CT DoC Enfield Small Arms Range North side of Sandhill Road	7/15/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to submit a plan to eliminate the risk to human health.	Impacted soil excavated and disposed off-site. No additional hazard abatement action necessary.
D and K Holdings Co., LLC 114 Broad Brook Road	9/16/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	DEP installs treatment systems at wells if found to be polluted above standards. DEP Consent Order with Town provides for subsequent connection of impacted and threatened homes to public water.
D and K Holdings Co., LLC 114 Broad Brook Road	11/12/2003	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to sample wells up to 1000 feet from the site for pollutants present at the site.	DEP installs treatment systems at wells if found to be polluted above standards. DEP Consent Order with Town provides for subsequent connection of impacted and threatened homes to public water.
Enrico Fermi High School 124 North Maple Street	4/4/2006	Pesticide pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.  Pollution detected in groundwater above standards may threaten a drinking water well.	DEP acknowledged actions already taken adequately limit access to polluted soil, and requested further study to delineate the problem and develop a remedy, and also evaluate potential impact on groundwater.	Field capped with 6 to 12 inches of clean fill to prevent direct exposure to impacted soil, other grassed areas also covered with clean fill.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Enfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
The Hanson-Whitney Company 116 Broad Brook Road	11/5/2003	Pollution was detected in a drinking water well above standards.	DEP recommended the continued use of bottled water. DEP is also currently evaluating reported pollution in this area.	Property now vacant with no water use. No additional hazard abatement action necessary. DEP investigation ongoing.

### Essex

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Tuscarora Incorporated (Former Verplex) 25 Middlesex Turnpike	3/3/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil had already been removed to a stockpile for off-site disposal. DEP directed the property owner to provide a report to DEP of the actions taken at the site.	Soil excavated from polluted area and stockpiled for disposal.

### Fairfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Railroad Bridge North Benson Road	1/3/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is in a restricted-access rail corridor, limiting the potential for contact.	Access is restricted because site is in fenced rail corridor; no specific hazard abatement action necessary.
Tide Mill 2425 Post Road	1/29/2009	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP reviewed sampling data and determined that the groundwater pollution does not in fact pose a significant threat to indoor air quality.	No specific hazard abatement action necessary
Universal Thread Grinding Company 30 Chambers Street	8/26/2002	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to submit a plan to determine if indoor air quality is being affected and, if so, recommend a course of action.	Soil vapor sampling performed, concentrations exceed soil vapor criteria, but not hazard thresholds. Potassium permanganate injection performed late 2007 to reduce concentrations of pollutants in groundwater. Additional injection proposed.

### Farmington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
College Highway Substation 201 Waterville Road	8/31/2004	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact.	Access is restricted; no specific hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Farmington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
commercial property 232 Colt Highway (Route 6)	1/24/2005	Pollution was detected in a drinking water well but is below standards, and other pollution detected in groundwater above standards may also threaten this drinking water well.	DEP determined that no action is required because the well is the only well in the area, is currently unused, and the detected pollution in it is significantly less than the standard.	Well not in use; no specific hazard abatement action necessary. DEP recommended retesting the well when it is again in service.
Farmington Automotive 352 Scott Swamp Road	2/21/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional sampling data for two threatened wells and found no pollution in the well water.	No additional hazard abatement action necessary
Mobil Service Station No. 01-QQF 435 Main Street	5/18/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to collect samples from the threatened supply well and provide an alternate supply of drinking water if contamination is detected.	Nearby supply well was sampled and no volatile organic chemicals were detected. On-site monitoring wells will continue to be sampled.
residential property 231 Coppermine Road	10/10/2002	Pollution was detected in a drinking water well but is below standards.	DEP reviewed sampling data and determined pollution is significantly below standards, and the water is safe for human consumption.	No specific hazard abatement action necessary.
residential property 74 West Avon Road	11/5/2004	Pollution was detected in a drinking water well, with some compounds above standards and other compounds below standards.	DEP directed the property owner to sample the polluted well quarterly and advise DEP of any changes.	A treatment system on the impacted well provides potable water. Supply wells on abutting properties have been tested and no pollution was detected.
		Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP determined the polluted soil has already been removed, eliminating the exposure risk.	Polluted soil removed; no hazard additional abatement action necessary.

### Franklin

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
7-Eleven 15 Route 32	4/12/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample potable water supply wells up to 500 feet away from the site for pollutants detected at the site.	Wells identified and sampled, pollution either not detected or detected but below standards.
7-Eleven 15 Route 32	8/1/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP required additional sampling of onsite and two nearby identified wells for pollutants detected at the site.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Franklin

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Kahn Tractor and Equipment 520 Pond Road	11/6/2007	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to identify potable water supply wells up to 500 feet away from the site and to sample downgradient wells pursuant to a plan previously approved by the Department.	Action pending.

### Glastonbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Best Cleaners 2759 Main Street	2/6/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the operator to implement their proposed actions, including an inventory and sampling of nearby potable water supply wells, and also evaluate the potential for vapor migration into buildings	Wells identified by investigation were sampled with no detection of pollution. Site is undergoing investigation and remediation under Property Transfer Program.
former Glastonbury Gage 184 Commerce Street	6/11/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs and install a fence or secure the area to limit contact with the polluted soil.	Polluted soil removed; no additional hazard abatement action necessary.
		Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to resample the groundwater to further evaluate the threat to surface water.	Well retested; source investigation ongoing under Property Transfer Program.
residential property 57 High Ridge Road	6/9/2005	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to sample the threatened wells periodically for pollutants detected at the site, and create a long-term monitoring plan.	Remedial system installed; residential water supply well sampled and no volatile organic compounds detected above standards. Also, no volatile organic compounds detected in most downgradient monitoring wells.
Shell Facility No. 136314 2088 Hebron Avenue	12/3/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Three wells identified and sampled, pollution not detected or significantly below standards. No further hazard abatement action necessary.

### Greenwich

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
HASCO Electric (former) 84 South Water Street	10/27/2006	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to determine the extent of groundwater and/or soil gas pollution exceeding the hazard threshold criteria, determine if indoor air is adversely affected, and identify drinking water wells within 500 feet.	Extent of groundwater and soil vapor exceeding hazard threshold criteria appears to be limited to the on-site building which remains vacant; no wells were identified within 500 ft.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Greenwich

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
High Tower Trading, LLC 1275 King Street	11/4/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to continue sampling the threatened wells for the pollutants detected at the site and advise DEP of any changes.	Action pending.
Ludor Corporation 371 East Putnam Avenue	8/7/2008	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP reviewed sampling data and determined that the groundwater pollution does not in fact pose a significant threat to indoor air quality.	No specific hazard abatement action necessary.
Riverside Cleaners (former) 1130 East Putnam Avenue	11/16/2007	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to determine if indoor air quality is being affected and, if so, provide a remedial action plan.	geophysical investigation to determine the placement of bedrock monitoring wells conducted in December 2007. Further investigation of the groundwater plume is underway.

### Griswold

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Griswold C-Store, LLC 659 Voluntown Road	6/17/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to resample the on-site well, and identify and sample wells up to 250 feet from the site, for pollutants detected at the site.	Wells identified and sampled, pollution either not detected or below standards.

### Groton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Colonial Apartments 2350 Gold Star Highway	3/5/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional sampling data showing that the well at risk was not polluted.	No additional hazard abatement action necessary. DEP recommended periodic retesting until remediation of the site is complete.

### Guilford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mobil Service Station No. 01-QBA 1164 Boston Post Road	7/1/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.
residential property 103 Daniel Avenue	6/23/2006	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to maintain and monitor an installed treatment system for the polluted well, provide a list of wells inventoried in the area, and expand the sampling program to other nearby wells.	A treatment system has been provided to remove constituents of concern from the affected water supply well.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Haddam

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Connecticut Yankee Atomic Power Co. 362 Injun Hollow Road	8/11/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to install a fence to limit access to the polluted soil until the site is cleaned up.	Polluted soil removed; no additional hazard abatement action necessary.
Jaspers (former) 206 Saybrook Road	12/31/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the former property owner to resample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.
Maple Avenue Area [Higganum] Maple Avenue [Higganum]	9/15/2005	Pollution was detected in drinking water wells above standards; also, pollution was detected in other drinking water wells but is below standards.	DEP directed the notifying party to provide bottled water to property with polluted wells above criteria, and to establish a long-term monitoring program for the impacted wells.	DEP provided a filter system to one residential property. DoT has provided bottled water to several businesses.
Mike's Auto Service LLC 1573 Saybrook Road	1/17/2007	Pollution was detected in a drinking water well but at a level substantially below standards.	DEP reviewed data for the affected well, and determined contamination in the well is significantly below standards, and the water is safe for human consumption.	No additional hazard abatement action necessary.
Tylerville BP [Facility #61-11042] (former) 1598 Saybrook Road	6/23/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well, sample wells within 500 ft. that have not yet been sampled, and provide sample results and a map of supply well locations previously identified.	Action pending.
uncertain parcel Haddam Neck Road	11/1/2006	Pollution above standards was detected in a total of six drinking water wells, two of which are not in use. Pollution below standards was detected in two drinking water wells.	DEP requested the notifier's client and/or property owner to provide an alternate supply of potable water to properties with wells polluted above Drinking Water Standards, and to provide a plan to monitor affected and potentially affected wells.	Wells in vicinity of a suspected release area have been identified and sampled; bottled water is being provided to affected residences.

### Hamden

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Cable's Property 87 Kimberly Road	8/21/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample any wells up to 750 feet away from the site for pollutants detected at the site.	In addition to the onsite well, one other well was identified within 750 ft., but it could not be sampled because the property is condemned. The onsite well was sampled and found pollutants at levels below drinking water standards.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Hamden

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Laurel View Country Club 310 West Shepard Avenue	6/30/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample onsite (if any) and nearby wells for pollutants detected at the site.	All wells reportedly sampled and pollution not detected. Monitoring program under evaluation.
		Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP indicated that notification regarding petroleum hydrocarbons in surface soil is not required under the law.	Not a defined significant hazard; no action required.

### Hartford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
151 New Park LLC 151 New Park Avenue	10/6/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to investigate site under the Property Transfer Program and maintain temporary containment with vegetation and fencing to limit access to polluted soil until exposure risk is eliminated.	Temporary containment in place with vegetation and fencing until site is remediated under the Property Transfer Program.
Hartford Economic Development Commission 13 Wolcott Street	11/25/2002	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined the polluted soil is under pavement and in a fenced area, limiting the potential for contact.	Access to polluted soil is limited; no specific hazard abatement action necessary.
residence 19 Julius Street	6/12/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to submit a work plan with a schedule to remove lead paint impacted soil.	All lead hazards have been abated to meet lead abatement program requirements.
residential property 514-516 Hillside Avenue	12/4/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to conduct work to mitigate lead paint contaminated soil proposed in a submitted soil abatement plan.	Action pending.
residential property 279-281 Sargeant Street	12/4/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is covered by plastic, limiting the potential for contact, and will be evaluated and removed upon completion of the painting project.	Area covered with temporary plastic tarp until soil removed pursuant to work plan.
South Meadows Station, Mid-Conn RRF Gate 20 Reserve Road	12/23/2002	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact.	Access to polluted soil is limited; no specific hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Harwinton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Harwinton Citgo 166 Burlington Road	7/19/2005	Pollution was detected in a drinking water well, with some compounds above standards and other compounds below standards.	DEP directed the property owner to sample the threatened wells periodically for pollutants detected at the site, and connect the affected property to municipal water service.	Investigated all wells and hooked up impacted wells to municipal water.
Harwinton Citgo 166 Burlington Road	4/15/2008	Pollution was detected in a drinking water well above standards. Pollution was detected in a different drinking water well but is below standards.	DEP directed the property owner to continue providing bottled water until a filter system is installed on the impacted well, and implement a monitoring program for threatened wells.	Bottled water provided pending water treatment system installation. Monitoring program continued for threatened wells.

### Hebron

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Hebron Citgo 70 Main Street	5/17/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Additional sampling conducted. Bottled water provided to properties where pollution was above standards pending water treatment system installations. Monitoring on-going for threatened wells.
Hebron XtraMart Route 66 and Route 316	12/23/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	Additional sampling conducted. Bottled water provided to properties where pollution was above standards pending water treatment system installations. Monitoring on-going for threatened wells.
Hebron XtraMart 37 Main Street	7/19/2006	Pollution was detected in a drinking water well but is below standards.	DEP required additional sampling of nearby identified wells within 500 feet for pollutants detected at the site.	Additional sampling conducted. Bottled water provided to properties where pollution was above standards pending water treatment system installations. Monitoring on-going for threatened wells.

### Kent

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Bull's Bridge Garage 337 Kent Road (US Route 7)	12/12/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to continue to sample the on-site supply well and to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.
Kent Substation Route 341	5/12/2004	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact.	Access to polluted soil is restricted because it is within a fenced electrical substation; no specific hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Killingly

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
commercial property 405 Lake Road	12/11/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to assess the impact to downgradient receptors in consultation with the DEP.	Several wells identified and 9 wells sampled, pollution either not detected or detected but below standards. Monitoring program implemented.
Dayville XtraMart 439 Hartford Turnpike (Rte 101)	8/25/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the polluted wells quarterly for the pollutants detected at the site. DEP also requested that the property owner implement a proposed soil vapor survey.	Action pending.
Hopkins Wellfield south of intersection Rt 12 and Rt 101	12/27/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the threatened and polluted wells periodically for the pollutants detected at the site, and advise DEP of any changes.	Action pending.
MPI Label Systems 24 Doring Drive	8/7/2007	Pollution was detected in a drinking water well above standards. Pollution was detected in a different drinking water well but is below standards.	DEP directed the property owner to provide bottled water to the properties with polluted wells.	Action pending.

### Ledyard

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mobil Home Park 940 Long Cove Road	4/9/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to provide treatment for polluted wells, and a report of additional actions taken.	Safe supply of drinking water provided.
		Pollution in top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined the polluted soil has been removed, eliminating the exposure risk.	Polluted soil removed; no additional hazard abatement action necessary.

### Lisbon

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Lisbon Mobil 107 River Road	4/22/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Madison

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
East River Foundry (former) 82 Nathans Lane	2/15/2005	Pollution detected in groundwater that discharges to surface water may pose a risk to aquatic life.	DEP directed the property owner to submit a plan to evaluate the pollution migration and the threat to surface water and aquatic life.	Property ownership transferred to Town of Madison, site investigation and remedial action to be taken by town as part of site redevelopment. See notification by town 4/5/2007.
East River Foundry (former) 82 Nathans Lane	4/5/2007	Pollution detected in groundwater that discharges to surface water may pose a threat to aquatic life.	DEP directed the property owner to evaluate the nature, extent and degree of groundwater pollution to determine the threat to surface water and aquatic life near the site, and also provide sample results for drinking water wells.	Polluted soil on site remediated; action pending on requested groundwater evaluation.

### Manchester

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
commercial property 5 and 7 Tolland Trunpike	2/21/2006	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to provide an alternate supply of potable water and identify wells within 500 feet.	No wells identified within 500 ft down gradient. A carbon filter system has been installed on the onsite impacted well.
commercial property 42 Prospect Street	10/16/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to install a fence and post signs around the impacted area. DEP also required submittal of receptor survey information and additional sampling of groundwater for lead.	Receptor survey was conducted and no potable supply wells were identified. Lead was not detected in the groundwater.
Dean Machine/Precision Metals Testing (former) 102 Colonial Road and 372 Progress Drive	11/15/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP indicated it is already aware of this condition; and that the party submitting the notification was not required to do so under the law.	Threatened well is monitored by the Town.
Gulf Gasoline Station 128 Tolland Turnpike	12/1/2004	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to resample the supply well periodically until a filter is installed or a public water connection is made.	Receptor survey was conducted identifying 2 potable wells. Wells were sampled for contaminant of concern and both were below drinking water action level.
Town of Manchester Charter Oak Well Field 192 Charter Oak Street	6/6/2008	Pollution was detected in a drinking water well but is below standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the Town to identify and sample other nearby supply wells and develop a work plan to investigate the source area of the pollution.	Receptor survey identified one private supply well; water sample did not detect contaminants above drinking water standards.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Mansfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Dick's Automotive 644 Middle Turnpike	12/14/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify wells up to 500 feet away from the site.	Action pending.
Husky Mobil 607 Middle Turnpike (Route 44) [Storrs]	12/27/2007	Pollution was detected in a drinking water well above standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.
Mobile Service Station No. 01-G1P 7 Storrs Road	8/30/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to provide a copy of the already completed sensitive receptor survey, and investigate sidegradient and downgradient surface water features within 500 feet of the release for signs of surface water contamination.	Action pending.
residential property 986 Storrs Road	10/17/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Additional sampling conducted, pollution not detected or below standards.

### Marlborough

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Old Marlborough Village	10/9/2002	Pollution was detected in a drinking water well but is below standards.	DEP reviewed information provided and determined the pollution in the well was below standards, and the water is safe for human consumption.	Further sampling to be conducted as part of public water supply monitoring as required by Department of Public Health.

### Middlebury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
TranFarm Associates I, LLC 124 Tranquility Road	9/4/2003	Pollution was detected in a drinking water well, with one compound above standards and one compound below standards.	DEP reviewed additional sampling data and determined pollution is significantly below standards, and the water is safe for human consumption.	No additional hazard abatement action necessary. DEP recommended periodic sampling for the pollutants detected at the site.

### Middletown

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Best Cleaners 522 South Main Street	2/28/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to implement their proposed plan which includes sampling the potable well identified.	Completing well inventory and Site Investigation.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Middletown

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Bill's Auto Parts 1462 Saybrook Road	11/18/2004	Pollution was detected in a drinking water well but is below standards, and other pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site, and to provide bottled water or treatment for property with polluted wells.	Bottled water provided pending water treatment system installation. Additional sampling pending.
Color Mart 41 Broad Street	3/22/2004	Pollution was detected in a drinking water well but is below standards.	DEP reviewed additional sampling data and determined pollution is below standards, and the water is safe for human consumption. DEP recommended periodic sampling of the well until completion of planned connection to public water.	No additional hazard abatement action necessary.
CT DoT Maintenance Facility Paddock Road	1/27/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample identified wells up to 500 feet from the site for pollutants detected at the site.	Additional sampling conducted, pollution detected but below standards.
Quality Insulation, Inc. 1996 Saybrook Road	4/29/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample all identified wells within 500 feet for pollutants detected at the site.	Wells identified and sampled. No additional hazard abatement action necessary.
Sumner Creet LLC 20 Mill Street	1/5/2007	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property to resample the groundwater to further evaluate the threat to surface water and aquatic life.	Second phase of work plan in progress.
Wesleyan University Long Lane Campus 170 Long Lane	5/17/2007	Presence of coal ash throughout the site may pose a risk to human health as a result of direct contact.	DEP directed the property owner to continue to provide information to the Department as part of a continued site wide investigation and remediation. The property is under DEP oversight for remediation due to a 1999 property transfer.	Investigation and remediation of the site continues under DEP oversight.

### Milford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
commercial property 561-587 New Haven Avenue	12/8/2006	Polluted soil gas beneath an occupied building could affect indoor air quality.	DEP directed the property owner to characterize the extent of impact on groundwater and soil gas, assess the indoor air quality, propose controls to mitigate this impact, and conduct an inventory of water supply wells within 500 feet of the site.	No potable water supply wells identified within 500 feet. Investigations performed to characterize the degree and extent of groundwater pollution resulting from releases at site. Sub-slab soil vapor sampling and indoor air monitoring performed.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Milford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
commercial property 561-587 New Haven Avenue	2/15/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.  Polluted groundwater beneath an occupied building could affect indoor air quality.	Notification of these conditions was not required. DEP directed property owner to submit letter report of their actions as stated in DEP's December 18, 2006 acknowledgement letter regarding similar environmental hazard condition.	No additional hazard abatement action necessary.
Devon Generating Station Naugatuck Avenue	10/19/2006	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post a sign, notify people with the potential for exposure to the surface soil, and maintain security around the site and the secondary containment around the tank to limit access to the surface soil.	Warning signs posted; notified people with the potential for contact; maintaining site security and secondary containment to limit the potential for contact with polluted soil. Collected additional samples to delineate the extent of polluted soil.

### Monroe

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Alpha Typesetting (former) 618 Main Street	7/6/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample nearby identified wells for pollutants detected at the site.	Action pending.
Cyclone Car Wash, LLC 178 Main Street	6/30/2006	Pollution detected in groundwater above standards may threaten a drinking water well.  Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed additional data and determined pollution from this source is not affecting nearby wells.  DEP determined that the reported soil pollutant is exempted from the requirement for notification.	No additional hazard abatement action necessary.  Polluted soil is not exposed at the surface or located within the top two feet, which is zone defined as a potential hazard condition.
residential property 1068 Monroe Turnpike	9/9/2005	Pollution was detected in a drinking water well but is below standards.	DEP reviewed additional sampling data for the affected well and determined that the reported pollution was not confirmed as present, and the water is safe for human consumption.	Periodic sampling being conducted by nearby property owner with a documented tank leak that could affect this well.
former BP Service Station No. 1122 172 Main Street	12/11/2002	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to conduct long term sampling of polluted wells for pollutants detected at the site, or to provide a safe supply of drinking water.	Periodic sampling being conducted.
residence 55 Sentry Hills Road	12/28/2007	Pollution detected in groundwater may threaten a drinking water well.	DEP directed the property owner to conduct a drinking water supply well inventory within a 500 ft radius of the property and sample on-site well and any at-risk wells for the pollutants detected at the property.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Monroe

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Route 25 Auto Collision 256 Main Street	8/7/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.
Route 25 Auto Collision 256 Main Street	1/7/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well quarterly for the pollutants detected at the site and report the results to DEP and the local Health Director.	Monitoring program implemented.

### Montville

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
ash disposal site 128 Moxley Road	5/29/2007	Pollution detected in groundwater above standards may threaten a drinking water well.  Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to fence the area, assess the potential for the contaminated surface water to impact an upgradient pond and water supply well, and develop a plan to abate impacted surface and ground water.	Action pending.
Bonville Brothers Property (former) 291 Maple Avenue	3/30/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Well inventory completed and 3 closest wells sampled for pollutants of concern. No pollutants were detected. DEP requested semi-annual monitoring of the 3 wells for a period of two years.
Shantok Motors 2246 Route 32	4/16/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the on-site supply well and to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	Wells identified and sampled, pollution not detected. No additional hazard abatement action necessary.

### Morris

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
East Morris XtraMart 109 Thomaston Road [E. Morris]	3/12/2004	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	Additional sampling conducted, pollution detected in only two wells below standards. Monitoring program implemented.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Naugatuck

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
former Karo Manufacturing Site 285 Great Hill Road	12/1/2003	Pollution was detected in a drinking water well above standards.	DEP installed water treatment systems at properties with polluted wells.	The Borough of Naugatuck is acting to provide a long-term safe supply of drinking water to properties with polluted wells or threatened wells.
Sarracco Mechanical Services, Inc. 71 Naugatuck Drive	9/29/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify wells within 1,000 ft of the site and to sample three identified nearby wells for pollutants detected at the site.	Wells sampled; pollution not detected or detected significantly below standards. No additional abatement action necessary.

### New Britain

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Brothers Dry Cleaners and Dyers, Inc. 234 North Street	7/29/2005	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to determine the extent of the problem and provide a plan of action.	Proposed plan to vent area and take additional samples of soil gas has been implemented.
The Commercial Foundry Companies 326 South Street	6/3/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is under a building and in a secure area, limiting the potential for contact.	No specific hazard abatement action necessary.

### New Canaan

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
CT DoT Maintenance Facility 47 Gerdes Road	12/20/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is under pavement and in a secure and fenced area, limiting the potential for contact.	No specific hazard abatement action necessary.

### New Fairfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Druck Incorporated 3 Dunham Drive	6/3/2005	Pollution detected in groundwater above standards may threaten drinking water wells.	DEP directed the property owner to sample the onsite and nearby identified wells within 500 feet for pollutants detected at the site.	All wells sampled, pollution not detected or significantly below standards. No additional hazard abatement action necessary.
Fairwood Shopping Ctr/Candlewood Playhouse State Routes 37 and 39	8/23/2005	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to submit a plan to continue quarterly monitoring of at-risk supply wells and provided bottled water for private residences with pollution over applicable criteria.	Water treatment system installed at one well. Monitoring program implemented for four threatened wells.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### New Fairfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mobil New Fairfield 01-E2E 94 State Route 37	10/12/2005	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to sample the onsite and nearby identified wells for pollutants detected at the site.	Monitoring program implemented. Water treatment system already installed at the polluted on-site well.
New Fairfield Police Department 302 Ball Pond Road	11/29/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to continue sampling wells already monitored, and sample additional nearby supply wells, for pollutants detected at the site.	Nearby wells sampled three times, pollution not detected. Additional investigation planned for site.

### New Haven

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Amtrack Cedar Hill Maintenance of Way Base 255 Welton Street Rear	2/17/2006	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to continue proposed actions and to inform persons with potential for exposure, post warning signs and install a fence to limit access to the polluted soil until the site is cleaned up.	Warning signs posted, site secured, and fence installed to limit the potential for contact with polluted soil.
parcel 370 James Street	10/27/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to identify the extent of polluted soil and remove the polluted soil.	Action pending.
Quinnipiac Energy English Station 510 Grand Avenue	3/1/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined the polluted soil is in a secure area, limiting the potential for contact. DEP directed the property owner to post warning signs and inform persons with potential for exposure.	Action pending.
Rockwell Heat Treating 194 River Street	10/31/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is in a secure and fenced area limiting the potential for contact. Per the notification, persons with potential exposure will be alerted, and warning signs will be posted.	Some polluted soil has been removed; the extent of the release area has been determined.
Simkins Industries, Inc. 260 East Street	11/18/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the soil pollution does not pose a significant threat because it is isolated under pavement.	No specific hazard abatement action necessary.
Troup Magnet Academy of Science 259 Edgewood Avenue	6/29/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to submit a plan to identify the extent of polluted soil and remove it.	Impacted soils were excavated in August/Sept 2006 and rendered inaccessible at the site as described in the Remedial Action Report prepared by consultant in January 2008. No additional hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### New Haven

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Williams Terminals Holdings, LP 85 East Street	11/25/2002	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs and install a fence or secure the area to limit access to the polluted soil.	Warning signs posted and fence installed to limit the potential for contact with polluted soil.

### New London

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Coca-Cola Bottling Co. of Southeastern New Englan 951 Bank Street	3/28/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is under pavement, limiting the potential for contact.	The polluted soil will be managed in the context of environmental work underway pursuant to the property transfer program. No specific hazard abatement action necessary.

### New Milford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
B&W, LLC/Wetmore's, Inc. 333 Danbury Road	5/20/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to re-sample the onsite supply well on a quarterly basis and to identify and sample nearby wells for pollutants detected at the site.	Quarterly monitoring program implemented.
Bulls Bridge Hydroelectric Station Route 7	4/13/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and to identify and sample wells up to 500 feet downgradient from the site for pollutants detected at the site.	On-site drinking water well and monitoring well resampled. Pollution was not detected. No additional hazard abatement action necessary.
Candlewood Animal Hospital 117 Kent Road Route 7	5/17/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and nearby wells for pollutants detected at the site and to conduct an inventory of all drinking water supply wells at residences and businesses within 500 ft of the release.	Action pending.
Century Enterprise Center (former Century Brass) 12 Scoville Street	12/9/2004	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to sample the polluted well quarterly for pollutants detected at the site, and advise DEP of any changes.	One well sampled. Pollution detected was significantly below standards. Monitoring program implemented.
industrial condominium 566 Danbury Road	12/6/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	All wells on-site and downgradient wells sampled, pollution not detected or was significantly below standards. One year of on-site monitoring shows that on-site well is not impacted. Will continue to sample monitoring wells near septic system.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### New Milford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
O & G Quarry 33 Boardman Road	5/24/2007	Pollution was detected in a drinking water well but is below standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite and identified wells within 500 feet for pollutants detected at the site.	Action pending.
residential property 53 Sawyer Hill Road	5/14/2004	Pollution was detected in a drinking water well but is below standards.	DEP determined that pollution in the well is below standards, and water is safe for human consumption.	Source of pollution removed. No additional hazard abatement action necessary. DEP recommended periodic monitoring.
Taylor's Cleaners 104 Danbury Road	3/13/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the four threatened wells identified in the significant hazard notification on a quarterly basis for the pollutants detected at the site.	Four wells sampled, pollution not detected or detected significantly below standards. Monitoring program implemented for wells with trace pollutants.

### Newington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Willard Avenue Substation Route 173	5/18/2004	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact with the polluted soil.	Access to polluted soil is restricted because it is within a fenced electrical substation; no specific hazard abatement action necessary.

### Newtown

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 53 Mile Hill Road South	12/5/2005	Pollution was detected in a drinking water well above standards.	DEP directed the residents to use bottled water until a filtration system could be installed. DEP will also be following up with an investigation to determine the source of pollution and with sampling at neighboring residences.	Drinking water wells in area identified and sampled with two found to have pollution above standards. Filtration system installed at two residences. Quarterly monitoring program implemented.
Rocky Glen Mill 75 Glen Road	12/28/2006	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to sample the onsite supply well on a quarterly basis and to identify wells up to 500 feet away from the site.	Receptor survey completed. Monitoring of onsite well is ongoing.
Sandy Hook Automotive and Marine Corp. 9 Glen Road [Sandy Hook]	3/28/2008	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to re-sample the on-site supply well and to identify and sample wells within 500 feet of the site for pollutants detected at the site.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Newtown

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
SCB Office Park 153 South Main Street	1/27/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs and install a fence to limit access to the polluted soil. DEP also directed the property owner to submit a plan to investigate the area and clean up pollution.	Warning signs posted and fence installed to limit the potential for contact with polluted soil. Additional assessment of area has been conducted.

### North Canaan

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
John B. Hull, Inc. 10 Orchard Street	1/27/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the threatened well quarterly for pollutants detected at the site, until clean up of pollution is complete.	One well identified. Well sampled for five quarters and pollution not detected. No further hazard abatement action necessary.
residential property 335 East Canaan Road	1/8/2003	Pollution was detected in a drinking water well but is below standards.	DEP reviewed sampling data and determined pollution in the well is significantly below standards, and the water is safe for human consumption.	No specific hazard abatement action necessary.

### North Haven

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Morganite Crucible 345 Washington Avenue	2/26/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs and install a fence to limit access to the polluted soil.	Polluted soil removed; no additional hazard abatement action necessary.
Pharmacia and Upjohn Company 41 Stiles Lane	2/28/2005	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to implement a proposed sampling program to evaluate the actual pollution concentration in the surface water.	Action pending.

### North Stonington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Prestonwold, Inc. 154 Miller Road	4/17/2003	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to provide bottled water to the property with the polluted well.	Additional sampling conducted, pollution below standards. Bottled water being provided.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Norwalk

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Norwalk Compressor Company (former) 20 North Water Street	2/27/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is under a building, limiting the potential for contact; and remediation to remove the soil is scheduled for 2008.	Action pending.
residential property 54 Nursery Street	10/13/2005	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to implement their proposed response, which is evaluation of additional sampling data to determine if treatment or additional monitoring is necessary.	On-site well sampled, pollution either not detected or detected but below standards. Source of pollution removed and passive remedial system installed. No additional hazard abatement action necessary.
The Fairfield County Savings Bank 26 Chestnut Hill Road	10/10/2003	Petroleum products in groundwater may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Additional sampling conducted, pollution not detected. Source of pollution removed.

### Norwich

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
7-Eleven Store No. 32524 152 Taftville Occum Road	6/24/2004	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to implement proposed quarterly sampling of the well for the pollutants detected at the site, and to provide a water treatment system if levels of pollution rise.	Further sampling to be conducted as part of public water supply monitoring as required by Department of Public Health.
Austin's Garage 53 Taftville-Occum Road	10/12/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site, and also to assess the potential for organic vapor intrusion at three addresses.	Nine wells were identified within 500 feet downgradient of the site. Volatile organic chemicals were not detected. Further evaluation of site data did not suggest a risk of vapor intrusion to nearby residences.
Norwich Fish and Game 44 Browning Road	10/28/2008	Pollution was detected in a drinking water well, but is below standards.	DEP requested that the City of Norwich evaluate potential impact to downgradient receptors in consultation with the DEP.	Action pending.
Thayer Building 16 Franklin Street	9/4/2002	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to determine if indoor air quality is being affected and provide a plan of action.	Plan of action submitted. Building vacant. Plan of action to be implemented as part of redevelopment.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Old Lyme

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Bestway Citgo Gasoline Service Station 281 Shore Road (Route 156)	9/8/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Sampling conducted, only one well had pollution above standards. Property with polluted well above standards is seasonal and vacant. Affected property connected to public water.

### Old Saybrook

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
CT DoT Maintenance Facility (former) 45 Ferry Road	10/11/2007	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to provide an alternate supply of potable water.	Bottled water provided pending connection to public water supply. DEP requested a technical report that analyzes potential for onsite pollution to affect the bedrock aquifer in vicinity.
Grossman Chevrolet 300 Middlesex Turnpike	4/21/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional sampling data and determined that groundwater pollution is in fact below standards, and does not threaten a supply well.	Nearest supply well tested with no pollution detected. No additional hazard abatement action necessary.
Grossman Chevrolet 300 Middlesex Trunpike	11/17/2005	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to sample the polluted well quarterly to ensure the installed filtration system is effectively removing contaminants of concern from the water supply.	Filter system was already installed on affected well. Source of pollution removed, further action including expanded onsite groundwater monitoring pending.

### Orange

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mobil Service Station No. 01-355 Wilbur Cross Parkway - Northbound	6/28/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the responsible party to identify and sample nearby wells for pollutants present on the site.	Action pending.

### Oxford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Quaker Farm Schools 30 Great Oak Road	12/20/2006	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to sample the out-of-use onsite supply well and to identify and sample nearby wells for pollutants detected at the site.	Groundwater treatment system in operation. Pollution not detected in two years monitoring nearest three drinking water wells. Sampling of indoor air shows air pollution is not at levels that pose a significant risk.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Plainfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
CT Property (Griswold Rubber Co. lease) River Street	2/8/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs and implement a proposed removal of the polluted soil.	Warning signs posted and mulch cover installed to limit the potential for contact; removal of soil pending.
Frybrook Substation 18 Community Avenue Extension	8/31/2004	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact.	Access to polluted soil is restricted because it is in a fenced electrical substation; no specific hazard abatement action necessary.
Griswold Rubber Company, Inc. 1 River Street	3/15/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to inform persons with potential for exposure, post warning signs and secure the area to limit access to the polluted soil until the site is cleaned up.	DEP's understanding is that the site has been posted. An abatement plan was proffered but rejected. Another is being developed.
parcel 154-156 Plainfield Pike	12/6/2004	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to submit a plan to identify the extent of polluted soil, limit access to the polluted soil, and test a nearby well for the pollutants present on the site.	Action pending.
Plainfield XtraMart Route 12 - 704 Norwich Road	11/22/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample wells on adjacent properties for pollutants detected at the site.	Action pending.
residence 484 North Main Street	11/20/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and downgradient supply wells for pollutants detected at the site pursuant to a remediation plan developed in consultation with the DEP and concurrent with the notification.	Action pending.

### Plainville

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
General Electric Company - North Plant Woodford Avenue	5/23/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample identified drinking water wells within 500 feet for pollutants detected at the site.	1 well has been identified and sampled by DEP, pollution not detected.

### Plymouth

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Grimes Aerospace Facility (former) 50 Altair Avenue	7/28/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample 17 nearby wells for pollutants detected at the site.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Plymouth

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
J. T. Mac Dermid Group 400 Harwinton Avenue	12/16/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 1000 feet from the site for pollutants detected at the site.	Additional sampling: 2 wells polluted above standards. Treatment system installed on one well; other well owner declined treatment but showering determined safe and is receiving bottled drinking water.
		Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to submit a plan to evaluate the threat to surface water and aquatic life.	Plan submittal pending.
proposed High School Site 564 Main Street	10/17/2002	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP indicated it is already aware of and is evaluating this condition; and that the party submitting the notification was not required to do so under the law.	DEP evaluating site.
Woodworking Design and Supply 284 Town Hill Road	9/25/2002	Pollution was detected in a drinking water well but is below standards.	DEP reviewed information provided and determined pollution in the well is significantly below standards, and the water is safe for human consumption.	Bottled water is being provided voluntarily by property owner, who will periodically resample the well. No specific hazard abatement action necessary.

### Portland

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 37 Maple Road	6/11/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells adjacent to both sides of the property	Property owner tested wells requested by the department and found no contamination above applicable standards.

### Preston

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Norwich State Hospital Route 12	2/9/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is in a secure, patrolled area, limiting the potential for contact.	Access is restricted; no specific hazard abatement action necessary.

### Putnam

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Gomes Total Chrysler 157 Providence Pike	6/23/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	Sampling conducted, pollution below standards. No additional monitoring required for hazard abatement.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Putnam

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Interstate Shell 647 School Street	2/17/2009	Pollution was detected in a drinking water well, but is below standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.
Kars of Putnam, LLC 181 Killingly Avenue	2/1/2006	Pollution detected in groundwater above standards may threaten drinking water supply wells.	DEP directed the property owner to sample the onsite supply wells and identify and sample nearby wells for pollutants detected at the site.	Wells identified and sampled, pollution not detected. No additional hazard abatement action necessary.

### Ridgefield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
commercial property Ethan Allen Highway	10/1/2007	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to provide the results of the receptor survey to the DEP.	According to the property owner, a charcoal filter has been installed on the drinking water supply system and a receptor survey has been initiated.
Exxon Service Station #3-6047 (former) 626 Danbury Road	4/8/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and also identified supply wells up to 750 feet away from the site for pollutants detected at the site.	Action pending.
Ridgefield European Motors, Inc. 746 Danbury Road	3/18/2008	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to maintain an existing treatment system, and also required identification and sampling of supply wells within 500 feet for pollutants detected at the site.	Action pending.
Shell Facility No. 136367 130 Danbury Road	10/12/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to resample the onsite well and to sample all identified drinking water supply wells within 500 feet of the site for the reported pollutants detected at the site.	Groundwater monitoring samples collected from site and neighboring potable well since SEHN report indicate that concentrations of compounds detected are less than applicable criteria.

### Rocky Hill

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Dividend Partners LLC 145 Dividend Road	3/16/2006	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to inform persons with potential for exposure, post warning signs and install a fence or secure the area to limit access to the polluted soil, and to submit a plan to evaluate and mitigate the hazard condition.	Fencing installed, warning signs posted. Plan to evaluate and mitigate hazard is forthcoming.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Rocky Hill

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Royal Clothing Care 825P Cromwell Avenue	8/22/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	2 drinking water wells identified. One well sampled, no analytes detected. Access denied to second well. Ongoing remediation being conducted under Property Transfer Program.

### Salem

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Maple Shade General Store 428 Hartford Road	4/11/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample potable water supply wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.

### Salisbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residence 433 Salmon Kill Road	10/25/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to resample the onsite supply well and to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	On-site and eight surrounding water supply wells sampled. Pollution not detected. Monitoring program implemented.

### Seymour

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Comcast 80 Great Hill Road	12/3/2007	Pollution was detected in a drinking water well but is below standards. Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to re-sample the onsite supply wells and to identify and sample nearby wells for pollutants detected at the site.	Action pending.
Diversified Electric 130 - 150 Silvermine Road	4/28/2008	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to re-sample the on-site supply well and to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Quarterly monitoring program implemented.

### Sharon

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Sharon Hospital 50 Hospital Hill Road	6/15/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the threatened well quarterly for the pollutants detected at the site.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Simsbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Shell Facility No. 136370 12 Albany Turnpike	12/29/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Additional sampling conducted, pollution detected above standards. Additional hazard notification submitted 04/15/2004.
Shell Facility No. 136370 12 Albany Turnpike	4/15/2004	Pollution was detected in a drinking water well above standards.	DEP reviewed additional sampling data, which showed pollution was below standards, and recommended additional sampling of well.	Filter was provided to the impacted well. Subsequent samples from the impacted well have indicated that petroleum hydrocarbons are not detected.

### Somers

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
495 Springfield Road 945 Springfield Road	8/8/2008	Fuel Oil detected in groundwater may threaten a drinking water well.	DEP directed the property owner to conduct quarterly monitoring of on-site and adjacent potable water supply wells and to continue monitoring an installed sub-slab depressurization system.	2/09 groundwater monitoring did not detect volatile organic substances or petroleum hydrocabons. Monitoring continuing.
Conval, Inc. 265 Field Road	7/16/2003	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Sampling conducted at one well, pollution not detected. Reports are provided to DEP and DPH. Looking to complete 1 year monitoring in 2009 with compliance to be to background

### South Windsor

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Ful-Line Auto 1546 John Fitch Boulevard	8/24/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to continue to sample the onsite supply well and identify wells up to 500 feet away from the site.	No drinking water supply wells identified within 500 ft. Onsite drinking water well sampled with no detections of volatile organic compounds.
Mobil 01-QQA 249 Oakland Road	6/11/2007	Petroleum products in groundwater treaten a drinking water well.  Surface water body is impacted by free product migrating from site.	DEP directed the property owner to implement a proposed plan to install a product recovery system, monitor potable water supply wells and continue to treat and monitor the impacted stream.	Installed product recovery system and sampled downgradient supply wells with no detection of petroleum products.

### Southbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
KAN-PAK 425 Main Street North	11/4/2002	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional information provided and determined the pollution does not pose a risk to supply wells.	No specific hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Southbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Regal Cleaners 220 Main Street South	5/14/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample wells identified within 200 feet of the site for pollutants detected at the site.	Wells sampled, one well above action level; DEP supplied treatment.
Shell Facility No. 136373 121 Main Street North	12/3/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed property owner to identify and sample nearby wells for pollutants detected at the site.	Wells sampled, No significant pollution detected.
Shepaug Hydroelectric Station 2225 River Road	4/5/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional sampling data for the threatened on-site well and determined that pollution is not, in fact, present in the well.	On-site well was sampled, and pollution was not detected. Bottled water is used for drinking water purposes. Long term monitoring is in place until site remediation complete.
Space Swiss 238 Reservoir Road	11/25/2003	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	All nearby residences now connected to public water. No further hazard abatement action necessary.
Space Swiss 238 Reservoir Road	10/6/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Three wells sampled, two had pollution above standards, bottled water provided pending long-term solution. Water supply line installed and affected residences connected. No further hazard abatement necessary.
Space Swiss 238 Reservoir Road	10/25/2004	Pollution was detected in drinking water wells, and some have pollution above standards.	DEP directed the property owner to identify and sample additional wells up to 1000 feet away from the site for pollutants detected at the site, and to provide bottled water or treatment to property with polluted wells above standards.	Water line extension completed. All contaminated wells closed. No further hazard abatement action necessary.

### Southington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Marion Mall XtraMart 2201 Route 322 (Meriden-Waterbury Turnpike)	9/3/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	No drinking water supply wells identified within 500 feet of the site. No further hazard abatement action necessary.
Milldale XtraMart 1611 Route 322 (Meriden-Waterbury Turnpike)	9/3/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	One drinking water supply well identified within 500 feet of the site. The location was vacant and as a result no sample was collected. Ongoing investigation.
New Star Dry Cleaners/Carriage Trade Cleaners 415 North Main Street	5/20/2003	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP reviewed sampling data and determined that the groundwater pollution does not in fact pose a significant threat to indoor air quality.	No specific hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Southington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Southington Water Pollution Control Facility 12 Maxwell Noble Drive	5/20/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to expand the barrier fence perimeter, install a temporary cover over highly PCB impacted soil (above 30 ppm), and provide a plan for short term and long term soil removal actions.	The area of elevated PCBs is located within the fenced facility. The majority of the area of elevated PCBs is isolated by a perimeter barrier.

### Sprague

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Pautipaug Country Club 7 Dows Lane	5/3/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample nearby wells for pollutants detected at the site, and to provide a plan to remove the source of the contamination.	Action pending.
Taylor Site 40 Hanover-Versailles Road	10/31/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Action pending.

### Stafford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
TTM Technologies 4 Old Monson Road	11/13/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to inform persons with potential for exposure, post warning signs and install a fence or otherwise secure the area to limit access to the polluted soil until the site is cleaned up.	Action pending.

### Stamford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
120 Long Ridge LLC, Parcel B-R 120 Long Ridge Road	9/25/2008	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP reviewed information provided and determined that the groundwater pollution does not in fact significantly threaten aquatic life.	No specific hazard abatement action necessary
120 Long Ridge Road LLC, Parcel B-R 120 Long Ridge Road	6/19/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample private supply wells up to 500 feet away from the site for pollutants detected at the site and provide alternative supply of potable water if necessary.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Stamford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Antares Gateway SPE, LP 424 Washington Boulevard	5/2/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and established that the polluted soil is in a secure and fenced area, limiting the potential for contact. DEP requested this security be maintained, and a report be submitted when planned remediation is completed.	No direct exposure pathway to polluted soil exists, and this security will be maintained until site is remediated. Remediation will be completed during re-development activities proposed for the site.
Antares Walter Wheeler Drive 69 Walter Wheeler Frice and 25 Washington Blv	7/5/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to delineate the extent of polluted soil and post warning signs, inform persons with potential for exposure, and maintain fence and asphalt cover to limit access to the polluted soil until the site is cleaned up.	Action pending.
Long Ridge Service 1095 Long Ridge Road	2/5/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite and identified wells within 500 feet for pollutants detected at the site.	33 wells identified and 20 wells sampled from all owners granting permission. Pollution from site not detected. No additional hazard abatement action necessary.
Pateley Associates, LLC 23 Barry Place	3/10/2006	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to inform persons with potential for exposure, post warning signs and maintain the pavement limiting access to the polluted soil until the site is cleaned up.	Additional investigations have been conducted. Onsite employees notified by tenant company of condition on 1/31/2006. Polluted soils are covered by asphalt pavement and site is secured, limiting potential contact with polluted soil.
residential parcel (source unknown) Diamondcrest Lane	7/7/2009	Pollution was detected in a drinking water well above standards.	DEP required additional sampling of the private well for total petroleum hydrocarbons 3 months after the initial sampling event to confirm that pollution is not in fact present in well.	Action pending.
residential property 216 East Middle Patent Road	9/6/2002	Pollution by fuel oil was detected in a drinking water well.	DEP directed the property owner to sample nearby wells for pollutants detected at the site, and to properly abandon the old on-site supply well.	Source of pollution removed. New well installed, and testing of it found no pollution. Additional sampling conducted, no pollution detected. Old well abandoned as required.
residential property 267 Thunder Hill Drive	12/23/2002	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional information and determined that the pollution release was limited, and that the threatened well was tested, with no pollution detected.	No additional hazard abatement action necessary. DEP recommended periodic sampling of the well.
residential property 75 Partridge Road	8/5/2004	Pollution was detected in a drinking water well above standards, and other pollution detected in groundwater above standards may threaten a drinking water well.	Homeowner uses bottled water and has a water treatment system. DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	Source of pollution remediated, five nearby wells tested for pollutants detected on site, concentrations below analytical detection limit.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Stamford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 90 Wellington Drive	3/23/2005	Pollution was detected in a drinking water well above standards.	DEP reviewed additional sampling data for affected wells and determined that pollution in the wells was not confirmed. DEP recommended additional sampling to verify actual water quality in the wells.	Source of pollution removed, DEP will coordinate further sampling to more conclusively determine water quality in the wells.
Stamford Industrial Park/Yale and Towne Complex	1/3/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to identify the extent of polluted soil, inform persons with potential for exposure, post warning signs, and maintain the fence and bituminous concrete to limit access to the polluted soil.	Action pending.
Stamford Industrial Park/Yale and Towne Complex Market, Henry, Canal and Pacific Streets	3/13/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to delineate the extent of polluted soil and inform persons with potential for exposure, post warning signs, and maintain the concrete slab to limit exposure to the polluted soil.	Action pending.

### Sterling

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 703 Margaret Henry Road	4/15/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the threatened wells periodically for the pollutants detected at the site, and advise DEP of any changes.	Action pending.

### Stonington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mon Ami French Cleaners (former) 11-13 Cottrell Street	12/5/2006	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to 1) determine if indoor air quality is being affected and, if so, recommend a course of action; 2) perform a water well inventory; and 3) assess impacts to surface water quality.	Action pending.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Stratford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
U.S. Chrome Corporation 175 Garfield Avenue	2/5/2004	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to submit a plan to investigate the extent and degree of groundwater pollution, and to evaluate the threat to surface water and aquatic life.	Action pending.

### Suffield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
rResidential property 1117 North Grand Street	8/15/2005	Pollution by fuel oil was detected in a drinking water well.	DEP directed property owner to continue to sample potable water supply wells and maintain treatment systems.	Treatment systems have been installed. Long-term monitoring and maintenance is conducted by responsible party under Order SRD-197.

### Thompson

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Johnson Corrugated Products 720 Thompson Road	2/23/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	Additional sampling conducted, only one well had pollution above standards. Property with polluted well provided with bottled water pending additional sampling. Additional hazard notification submitted 7/13/2004.
Norampac Thompson Inc. 720 Thompson Road	7/13/2004	Pollution was detected in a drinking water well above standards.	DEP directed property owner to conduct sampling of additional wells and install water treatment system if pollution confirmed.	Bottled water being provided to properties with polluted wells. Additional sampling to be conducted.

### Tolland

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Mobil Service Station No. 01-328 56 Merrow Road	1/3/2003	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to conduct periodic well sampling for pollutants detected at the site.	Additional sampling conducted, pollution remains below standards.
Tolland XtraMart 153 Hartford Turnpike	9/22/2005	Pollution was detected in a drinking water well but is below standards, and other pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed the data provided and concluded water in the supply well is potable. DEP directed the property owner to implement their proposed plan to study groundwater on-site and re-sample nearby supply wells to confirm groundwater quality.	Wells identified and sampled, pollution either not detected or detected but below standards.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Torrington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
D'Angelo Property 981 Torrington Street	8/4/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed information provided and determined that the property with the threatened well is vacant and the well is disconnected from the house.	Well not in use; no specific hazard abatement action necessary.
former IMI Cornelius Wilshire Facility 2788 Winsted Road	8/22/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil has been removed, eliminating the exposure risk.	Polluted soil removed; no additional hazard abatement action necessary.
Northside Drive Area Northside Drive	4/23/2004	Pollution was detected in a drinking water well above standards.	DEP provided bottled water and conducted additional sampling. DEP reviewed additional sampling and determined the well's water is not polluted above standards.	Reported problem is not caused by pollution. No additional hazard abatement action necessary.
Northside Drive Area Northside Drive	5/14/2004	Pollution was detected in a drinking water well above standards.	DEP provided bottled water and conducted additional sampling. DEP reviewed additional sampling and determined the well's water is not polluted above standards.	Reported problem is not caused by pollution. No additional hazard abatement action necessary.
Northside Drive Area 60 Northside Drive	6/9/2004	Pollution was detected in a drinking water well above standards.	DEP provided bottled water and conducted additional sampling. DEP reviewed additional sampling and determined the well's water is not polluted above standards.	Reported problem is not caused by pollution. No additional hazard abatement action necessary.
residence 30 Apter Drive	10/20/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify wells within 500 feet and sample the closest downgradient potable water supply well.	No volatile organic compounds detected in identified and sampled downgradient wells; impacted soil removed and passive venting system installed. No additional hazard abatement action necessary.
Torrington Company Standard Plant (former) 59 Field Street	4/8/2004	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to determine if indoor air quality is being affected and provide a plan of action.	Additional sampling showed pollution does not pose a significant risk to indoor air quality.
Wilson Dodge and Nissan 1530 East Main Street	2/26/2003	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	All identified wells that granted access were sampled for the contaminants of concern. Lead identified in the first sampling round was determined to be due to sampling error. All sampled supply wells were non-detect for the contaminants of concern.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Union

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Union School 18 Kinney Hollow Road	5/21/2008	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to maintain an existing filter and identify and sample nearby wells.	Fence already installed, other action pending.
		Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs, install a fence to limit access to polluted soil, and submit a surface soil removal plan.	

### Vernon

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
former Texaco Facility No. 100037 444 Hartford Turnpike	2/18/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample nearby wells for pollutants detected at the site.	Additional sampling conducted, no site-related pollutants detected. Other pollutants were detected but are below standards. No further hazard abatement action necessary.
Mobil 01-QQQ Vernon 1292 Hartford Turnpike	2/15/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to continue to monitor offsite monitoring wells and to sample residential drinking water wells if the monitored wells become impacted.	Continuing to sample on-site and off-site monitoring wells. Latest report received in 6 /09 and 2/09.

### Voluntown

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Hartikka Tree Farm 262 Wylie School Road	6/20/2006	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.

### Wallingford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Barberino Property (former) Pent Road	6/9/2005	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to resample the groundwater to further evaluate the threat to surface water and aquatic life.	Action pending.
Century Fireplace Furnishings 856 North Main Street Ext.	9/29/2006	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP reviewed sampling data and determined that the groundwater pollution could pose a significant threat to indoor air quality.	A sensitive receptor study will be completed and a subslab depressurization system will be installed.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Wallingford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Cytec Industries South Cherry Street	4/7/2009	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to submit a plan to identify the extent of polluted soil, notify site occupants, and limit access to the polluted soil.	A temporary cover and piping were placed over the test pit location and warning signs were posted, site was secured, and additional fencing was installed in the test pit area to limit the potential contact with polluted soil.
fmr Marquette Medical Systems/Corometrics Facility 61 Barnes Road Industrial Park North	5/18/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet from the site for pollutants detected at the site.	Action pending.
Masonic Healthcare Center 22 Masonic Avenue	12/19/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs and inform persons with potential for exposure.	Access is restricted; no specific hazard abatement action necessary.

### Washington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Washington Depot (former) 1 Green Hill Road	4/1/2008	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample nearby wells for pollutants detected at the site.	All downgradient water supply wells sampled; pollution was not detected. A monitoring program was implemented.
Washington Substation Route 47	5/12/2004	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact.	Access to polluted soil is restricted because it is in a fenced electrical substation; no specific hazard abatement action necessary.
Washington Supply Company, Inc. property 2 Calhoun Street	12/23/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Judea Water Co Water Supply Well #2 and 2 existing private drinking water supply wells sampled. All results were "non-detect" for contaminants of concern. No additional hazard abatement action necessary.

### Waterbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Chase Collegiate School 565 Chase Parkway	10/5/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP determined that polluted soil is under pavement and extent of polluted soil is delineated. DEP directed property owner to submit plan to notify persons with potential for exposure, to install fence, and to remove polluted soil.	Polluted soil removed; no additional hazard abatement action necessary.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Waterbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
commercial property 1713 Thomaston Avenue	4/14/2009	Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP reviewed information provided and determined that the groundwater pollution does not in fact significantly threaten aquatic life.	Groundwater threat to surface water evaluated for site specific conditions and determined to not significantly impact surface water and aquatic life.
former PGP Industries, Inc. 46 Municipal Road	9/25/2002	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is under pavement and in a fenced area, limiting the potential for contact.	Access to polluted soil is limited by pavement. Property is unoccupied and secured.
Haydon Switch and Instrument, Inc. 1500 Meriden Road	10/26/2005	Polluted groundwater and soil vapor beneath an occupied building could affect indoor air quality.	DEP directed the property owner to identify private drinking water wells up to 1/4 mile away from the site; and to submit a plan to monitor groundwater, to characterize the impact on indoor air quality, and to develop a remedy to limit the impact.	No wells were found to be within 500 feet of the groundwater pollution. Vent system installed to prevent impact on indoor air quality. Groundwater monitoring ongoing. No additional hazard abatement action necessary.
Uconn Waterbury Campus (former) 32 Hillside Avenue	6/8/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to inform persons with potential for exposure by posting warning signs and installing a fence to limit access to polluted soil until the site is cleaned up and to submit a plan to identify the extent of polluted soil.	Fence installed and warning sign posted to limit access to polluted soil.
Yankee Gas Work Center 47 Eagle Street	3/31/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to inform site workers, post warning signs, and install a fence or secure the area to limit access to the polluted soil.	Warning signs posted and fence installed to limit the potential for contact with polluted soil.
Yankee Gas Work Center 47 Eagle Street	9/2/2003	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is in a secure and fenced area, limiting the potential for contact. DEP directed the property owner to post warning signs.	Impacted soil is currently being remediated under a Voluntary Remediation program.

### Watertown

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Eyelematic Manufacturing Corp. Inc. 1 Seemar Road	10/18/2005	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to identify private drinking water wells up to 1/4 mile away from the site; and to submit a plan to characterize the impact on indoor air quality and develop a remedy to limit the impact.	No drinking water wells identified within 1/4 mile. Monitoring wells installed at downgradient property line. Sub-slab depressurization system installed to limit vapor migration into building.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Watertown

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Polk Elementary School 435 Buckingham Street	3/7/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to post warning signs and maintain security of the area to limit access to the polluted soil until the site is cleaned up. DEP directed the property owner to identify potable wells up to 500 feet away from the site.	Warning signs posted and access is restricted. Soil removal pending.
residential property 1650 Litchfield Road	3/28/2006	Pollution was detected in a drinking water well but is below standards.	DEP reviewed the sampling data for the contaminated well and determined pollution in the well is at trace levels, significantly below standards, and that the water is safe for human consumption. Additionally, a water treatment system is in operation.	Source of pollution removed and soil vapor extraction and water treatment systems already in place. Monitoring data shows affected well is significantly below standards. No additional hazard abatement action necessary.
Ten Acre Mall 595 Straits Turnpike	6/19/2009	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to submit a plan to delineate the extent of the groundwater plume and to evaluate the potential impact on nearby residences.	Action pending.
Winchester Electronics Facility 400 Park Road	8/10/2004	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 1000 feet from the site for pollutants detected at the site.	Potentially impacted supply wells were sampled. No pollutants were detected. Investigation and remediation (if needed) of site continues under Property Transfer Program.

### West Hartford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Goodrich Pump and Engine Control Systems Charter Oak Boulevard	7/25/2005	Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP directed the property owner to determine if indoor air quality is being affected and provide a plan of action.	Action pending.
Goodrich Pump and Engine Control Systems Charter Oak Boulevard	11/10/2005	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that the polluted soil is under pavement, limiting the potential for contact.	Access to polluted soil is limited; no specific hazard abatement action necessary.
Jacobs Manufacturing (former) 176 Newington Road	6/22/2006	Polluted groundwater near or beneath an occupied building could affect indoor air quality.	DEP directed the responsible party to submit a schedule for the necessary work to address the groundwater contamination issue and determine if there are any downgradient receptors impacted by the release.	Soil vapor under building tested, and found to be below criteria.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### West Hartford

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Jacobs Manufacturing site (former) 176 Newington Road	12/6/2007	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to assess the extent and degree of PCB contamination within the impacted areas and conduct soil removal and disposal were necessary in accordance with current standards and regulations.	Action pending.

### West Haven

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Baker Properties 351 Morgan Lane	7/25/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to submit a plan to identify the extent of polluted soil and remove the polluted soil.	Action pending.
Superior Cleaners 900 Orange Street	5/23/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Two residential water supply wells identified with solvent pollution above action levels. Carbon filters installed at both homes, with quarterly monitoring.
Superior Cleaners 900 Orange Street	2/6/2006	Pollution was detected at a level above standards in a drinking water well.	DEP directed the property owner to provide an alternate supply of potable water to affected property, and to provide an inventory of all drinking water supply wells within 500 feet, test results for these wells, and status of any untested wells.	Inventory completed and carbon filter installed.

### Westbrook

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Westbrook XtraMart 130 Boston Post Road	2/11/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the responsible party to submit an already completed sensitive receptor survey, analytical results for two potable water supply wells already sampled, and proof that a third potable water supply well did not exist.	Action pending.

### Weston

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residence 6 Old Orchard Drive	2/2/2009	Pollution was detected in a drinking water well above standards.	DEP directed the property owner to sample the onsite well for pollutants detected at the site.	Oil impacted materials removed. Former water supply well sampled, pollution identified. Well bailed, re-sampled no pollution detected. No pollution detected in active supply well.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Weston

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 20 Old Stage Coach Road	10/24/2002	Pollution was detected in a drinking water well but is below standards.	DEP reviewed sampling data and determined pollution in the well is significantly below standards, and the water is safe for human consumption.	A water treatment system is installed; no specific hazard abatement action necessary.

### Wethersfield

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Wilkus Farm 138 Willow Street	7/9/2009	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Action pending.
William Street Regulator Station 23 Williams Street	1/29/2004	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP reviewed information provided and determined that warning signs are posted and the polluted soil is in a secure and fenced area, limiting the potential for contact.	Access to polluted soil is restricted because it is in a fenced utility station; no specific hazard abatement action necessary.

### Willington

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
I-84 TravelCenter 327 Ruby Road	9/4/2002	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional sampling data and determined that pollution in the water supply system water, as delivered to the tap, is below standards.	Further sampling to be conducted as part of public water supply monitoring as required by Department of Public Health.

### Wilton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residence 30 Quail Ridge Road	12/16/2008	Pollution was detected in a drinking water well above standards.	DEP directed the local Health Department to provide an alternate supply of potable water to the property owner and resample the well. DEP also directed the Health Department to identify and samples wells up to 0.75 miles from the Wilton Landfill.	All wells sampled, pollution triggering the hazard notification was not detected in subsequent testing (three rounds) of the well at 30 Quail Ridge Road . Monitoring program implemented and continues at the closed Wilton Landfill.
residential property 23 Rossimur Court	11/22/2002	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP reviewed additional sampling data for the threatened well and determined that the presence of pollution was not confirmed.	A water treatment system is installed; no additional hazard abatement action necessary. DEP recommended periodic well testing.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Wilton

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 68 Pipers Hill Road	11/22/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to resample the on-site supply well and sample any water supply well within 500 feet of the site for pollutants detected at the site and investigate groundwater quality downgradient of the release location.	Source of pollution removed, and monitoring data shows affected well and groundwater are below standards. No additional hazard abatement action necessary.

### Winchester

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
New England Bark Mulch 167 Torrington Road	10/20/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Onsite supply well contained no contaminants above standards. Pollution source was removed and site is undergoing groundwater monitoring. No off-site wells identified as at-risk. No additional hazard abatement action necessary.
Winchester XtraMart 102 Colebrook River Road	1/11/2007	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify the nearest downgradient offsite well and test it for volatile organic compounds and petroleum, and also to provide a map of groundwater flow directions.	Groundwater flow direction determined and no downgradient drinking water wells identified within 500 ft. Scope of work submitted indicating that further investigation of pollution is pending.

### Windsor

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Konica Minolta Business Solutions USA, Inc. 550 Marshall Phelps Road	9/5/2008	Pollution in the top two feet of soil may pose a risk to human health as a result of direct contact.	DEP directed the property owner to implement a proposed action plan that includes removal of impacted soil and collection of post remedial soil samples.	550 gallon underground tank and 20-30 cubic yards of soil were removed in 12/08.

### Wolcott

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Eagle Cleaners 372 Wolcott Rd	1/17/2007	Pollution was detected in a drinking water well but is below standards.	DEP directed the property owner to resample the onsite supply well and identify and sample wells up to 500 feet away from the site for pollutants detected at the site.	Property connected to municipal water 4/07. Additional investigation results submitted 5/16/07. Only two wells sidegradient to pollution are still unsampled.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Wolcott

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Max's Wolcott Gulf 685 Wolcott Road	1/3/2005	Pollution was detected in a drinking water well above standards; and in another drinking water well pollution was detected but was below standards.	DEP directed the property owner to continue providing bottled water to property with polluted wells above standards, and continue the current monitoring program for other wells in the area.	All identified affected properties connected to public water. No additional hazard abatement action necessary.
Max's Wolcott Gulf 685 Wolcott Road	1/11/2005	Pollution was detected in a drinking water well but is below standards.	See above response for 1/3/2005 significant environmental hazard notification.	See above action for 1/3/2005 significant environmental hazard notification.

### Woodbridge

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
residential property 78 Ansonia Road	1/30/2006	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to resample the onsite supply well and identify and sample nearby wells for pollutants detected at the site.	Action pending.
Town of Woodbridge Dog Pound 135 Bradley Road	1/14/2003	Pollution was detected in a drinking water well but is below standards.	DEP reviewed additional sampling data and determined that pollution in the well is significantly below standards, and the water is safe for human consumption.	No additional hazard abatement action necessary.
Town of Woodbridge Public Works 15 Meetinghouse Lane	9/20/2002	Pollution was detected in a drinking water well but is below standards.	DEP determined that pollution in the well is significantly below standards, and the water is safe for human consumption.	Source of pollution remediated; no additional hazard abatement action necessary. Monitoring ongoing.

### Woodbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Connecticut Tube Products 194 Old Town Farm Road	3/27/2007	Pollution detected in groundwater above standards may threaten a drinking water well.  Pollution detected in groundwater that discharges to a surface water body may pose a risk to aquatic life.	DEP directed the property owner to sample the onsite supply well and identify and sample nearby wells.  DEP also requested resampling of the groundwater to further evaluate the threat to surface water and aquatic life.	Groundwater threat to surface water evaluated for site specific conditions and determined to not significantly impact surface water and aquatic life.
Dom's Lynn's Corner Deli 1633 Main Street North	6/21/2005	Pollution detected in groundwater above standards may threaten a drinking water well.	DEP directed the property owner to identify and sample wells onsite and up to 500 feet away from the site for pollutants detected at the site.	Five drinking water wells and station well sampled, all had no significant pollution detected. One nearby property refused access for sampling.

## List of Significant Environmental Hazards Reported to the DEP

Period covering 8/01/2002 through 7/31/2009

### Woodbury

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Woodbury Mobil 718 Main Street South	3/19/2004	Pollution detected in groundwater above standards may threaten a drinking water well.  Polluted groundwater beneath an occupied building could affect indoor air quality.	DEP reviewed additional actions taken and determined that they adequately address the reported hazard conditions.	At-risk wells sampled with no pollution detected, except in a well already with treatment system. Vent system operated to prevent impact on indoor air quality until 2006 when groundwater quality improved. No additional abatement action required.

### Woodstock

<i>Site/location</i>	<i>Date Notified</i>	<i>Type of Hazard</i>	<i>Response</i>	<i>Action</i>
Woodstock Dept. Public Works Garage 215 Coatney Hill Road	5/19/2006	Pollution other than a substance for which the commissioner has established a ground water protection criterion was detected in a drinking water well.	DEP directed the property owner to sample the onsite supply well and identify and sample wells up to 1000 feet away from the site for sodium and chloride.	Wells identified and sampled. Monitoring program implemented.